

CORCORAN GALLERY OF ART

Washington, DC

Northwest corner of building

Photo by Corcoran Gallery staff, date unknown



Set back of 14th Street facade

Corcoran Gallery of Art

October 1990


Photo: Diana Hilden







ERNEST FLAGG INV.  
MDCCCXCIII




Detail 17th Street Facade showing Ernest Flag 'Signature'

Corcoran Gallery of Art

October 1990

Photo: Debra Allison



CORCORAN GALLERY OF ART  
Washington, DC  
Main entry on 17th Street  
Photo by Debra Alderson, October 1990





Detail of over door, 17th Street entrance

Cornwall Gallery of Art

October 1990

Photo: Debra Alderson



CORCORAN GALLERY OF ART  
Washington, DC  
Atrium and grand staircase  
Photo by Debra Alderson, October 1990



CORCORAN GALLERY OF ART  
Washington, DC  
Double height atrium, lower level  
Photo by Debra Alderson, October 1990





CORCORAN GALLERY OF ART  
Washington, DC  
Double height atrium, second level  
Photo by Debra Alderson, October 1990



Interior view of Waddy B. Wood's renovation of the Hemicycle  
Corcoran Gallery of Art

Photo courtesy of Corcoran Archives

Photo by Corcoran staff